

1020 and 1035 are most popular materials to produce adapter sleeves unless there is a special requirement.

Adapter sleeve

- Sleeve bushing: 1020/1035
- Bearing lock nut: 1020/1035
- Bearing lock washer: 1020/1035

Withdrawal sleeve

- Sleeve bushing: 1020/1035